



Standard wiring code

Models	Lead	6 Pin Connector	Cable Outside "Transparent"	Cable Outside „Black“	
MDA42X	Signal (+)	A	Yellow	Red	
MDA46X	Signal (-)	B	Grey	Black	
MDT42XX	Excitation (+)	C	White	White	
MDT46XX	Excitation (-)	D	Green	Green	
EPR	Calibration	E	Brown	Blue	
Serie	Calibration	F	Pink	Orange	

Models	Lead	8 Pin Connector	Cable Outside "Transparent"	Cable Outside „Black“	
PT 420	Excitation (+)	A	White	White	
PT 410	Signal (+)	B	Yellow	Red	
PT 412	Excitation (-)	C	Green	Green	
PT 450	Signal (-)	D	Grey	Black	
	Calibration	E	Brown	Blue	
	Calibration	F	Pink	Orange	
	Unused	G			
	Unused	H			